37 Brook Avenue, Maywood, New Jersey 07607 • (201) 368-9171

Date:

3/31/08

Engineer:

Larry Cuccio

Page:

1 of 5

To:

Distribution

Product:

SE-79HD System Expander

Symptom:

Loss of vertical sync in video in the LCD Viewfinder


To upgrade the SE-79D System Expander to accept all formats, a new multi-format Video Board is installed. Occasionally, a problem can occur where vertical sync is lost in the VF video, resulting in an unstable, rolling image. This problem occurs only in the multi-format video board with PCB # PE6411E. To correct this problem, two resistors, R527 (33K ohm) and R554 (33K ohm) will need to be changed to 15K ohm values.

Modification Procedure

- 1. Remove the video board. It is located in the rear of the system expander, on the left side behind the panel with the VF aspect control and tally light. Loosen three screws to remove this panel. (Refer to Fig. 1, control location 12, for panel location).
- 2. Remove resistors R527 and R554. Refer to Fig. 2 for their location.
- 3. Replace with 15K ohm resistors.


Replacement Components

Resistor, 15K ohm, P/N RGC1/16C 153D



- ① VF POWER switch and Indicator
- 2 FRONT TALLY switch
- 3 VF IND switch
- **4** HEAD POWER indicator
- **⑤ MENU switch**
- **6 MENU SELECT switch**

- **⑦ CURSOR controls**
- **® VF DTL LEVEL control**
- 9 VF SELECT switches
- **® SCRIPT connector**
- 1 RET SW connector
- 1 VF ASPECT switch






Fig 2

